

## CIRRICULUM VITAE

### SAHIL SANTOSH KHEUR

R/3, Yashwant Adarsh Colony, Bhimnagar, Sarvodaya Sadan Road,

Ghatkopar (W), Mumbai – 400 086.

Email ID – [sahilkheur56@gmail.com](mailto:sahilkheur56@gmail.com) Mob No. : +91 82914 97151. Passport No.: W3200517

#### PERSONAL DETAILS

- Date of Birth: 11<sup>th</sup> Nov 1998.
- Marital Status: Unmarried
- Nationality: Indian
- Gender: Male
- Countries of Work Experience:

Sr. No.	Country	Work Experience
1	India	2 Year, 1 Months
2	Philippines	3 Months
3	Sri Lanka	1 Month

- Languages :

Language	Read	Speak	Write
English	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Marathi	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Hindi	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

#### QUALIFICATION DETAILS

Course	Institute / University	Year of Passing	Percentage
B.E. Civil	G.V. Acharya Institute of Engg & Technology. (University of Mumbai)	2021	71%
D.C.E.	Veer mata Jijabai Technological Institute.	2018	56%
S.S.C.	Shivaji Shikshan Sanstha Multipurpose Technical Highschool	2014	84.80%

- **Technical Skills :**

- AutoCad 2D.
- LibreCad 2D.
- M.S. Word.
- M.S. Excel.
- M.S. Powerpoint.

## WORK EXPERIENCE

Name of the Project	Structural Audit of Residential Quarters of HPCL at Mumbai.
Year	2022
Location	Mumbai, Maharashtra.
Name of the Client	HPCL.
Project Feature	Non-destructive testing, visual inspections, Preparation of BOQ, Remedial Measures for repairs.
Position Held	Assessment Engineer
Activities Performed	Non-destructive testing, visual inspections, preparation of audit report, remedial measures for repair and BOQ with supporting calculations

Name of the Project	Preliminary Inspection at APM Terminal.
Year	2022
Location	Mumbai, Maharashtra.
Name of the Client	APM Terminal.
Project Feature	Preliminary Inspection.
Position Held	Assessment Engineer
Activities Performed	Inspection, preparation of inspection report.

Name of the Project	Condition Assessment of Concrete Structures at Ravva Onshore Terminals.
Year	2022
Location	East Godavari District, Andhra Pradesh.
Name of the Client	Cairn Vedanta
Project Feature	Non-destructive testing, visual inspections, Preparation of BOQ, Remedial Measures for repairs.
Position Held	Project Manager
Activities Performed	Non-destructive testing, visual inspections, preparation of audit report, remedial measures for repair and BOQ with supporting calculations

Name of the Project	Condition Assessment & Specialised Nature of Test for Corrosion Mapping at SVNIT campus Surat.
Year	2022
Location	Surat, Gujarat.
Name of the Client	NBCC.
Project Feature	Non-destructive testing, visual inspections, Preparation of BOQ, Remedial Measures for repairs.
Position Held	Project Manager.
Activities Performed	Non-destructive testing, visual inspections, preparation of audit report, remedial measures for repair and BOQ with supporting calculations

Name of the Project	NDT & Structural Audit of Staff Quarters of NABARD at Chennai.
Year	2022
Location	Chennai Central.
Name of the Client	NABARD Chennai.
Project Feature	Non-destructive testing, visual inspections, Preparation of BOQ, Remedial Measures for repairs.
Position Held	Project Manager.
Activities Performed	Non-destructive testing, visual inspections, preparation of audit report, remedial measures for repair and BOQ with supporting calculations

Name of the Project	Health Study & Rehabilitation Measures of NPK, NPK Bagging & Phosphoric Acid Plant at FACT, Cochin.
Year	2022
Location	Kochi, Kerala.
Name of the Client	FACT Cochin.
Project Feature	Non-destructive testing, visual inspections, Preparation of BOQ, Remedial Measures for repairs.
Position Held	Project Manager.
Activities Performed	Non-destructive testing, visual inspections, preparation of audit report, remedial measures for repair and BOQ with supporting calculations

Name of the Project	Structural Audit of NABARD RO Punjab at Chandigarh.
Year	2022
Location	Chandigarh, Punjab.
Name of the Client	NABARD Punjab.
Project Feature	Non-destructive testing, visual inspections, Preparation of BOQ, Remedial Measures for repairs.
Position Held	Project Manager.
Activities Performed	Non-destructive testing, visual inspections, preparation of audit report, remedial measures for repair and BOQ with supporting calculations

Name of the Project	Condition Assessment of Jetty of Adani Petronet at Dahej.
Year	2023
Location	Dahej, Gujarat.
Name of the Client	Adani Dahej.
Project Feature	Non-destructive testing, visual inspections, Preparation of BOQ, Remedial Measures for repairs.
Position Held	Project Manager.
Activities Performed	Non-destructive testing, visual inspections, preparation of audit report, remedial measures for repair and BOQ with supporting calculations

Name of the Project	Condition Assessment & Structural Stability of Admin Building & ECF Plant at Ratnagiri.
Year	2023
Location	Ratnagiri, Maharashtra.
Name of the Client	Finolex, Ratnagiri.
Project Feature	Non-destructive testing, visual inspections, Preparation of BOQ, Remedial Measures for repairs.
Position Held	Project Manager.
Activities Performed	Non-destructive testing, visual inspections, preparation of audit report, remedial measures for repair and BOQ with supporting calculations

Name of the Project	Plant Wide Structural Assessment of All concrete & Steel Structures installed in Plant at PASAR, Philippines.
Year	2023
Location	Philippines.
Name of the Client	PASAR.
Project Feature	Non-destructive testing, visual inspections, Preparation of BOQ, Remedial Measures for repairs.
Position Held	NDT In Charge.
Activities Performed	Non-destructive testing, visual inspections, preparation of audit report, remedial measures for repair and BOQ with supporting calculations

Name of the Project	Condition Assessment of Jetty of Port of Colombo at Colombo.
Year	2023
Location	Colombo, Sri Lanka.
Name of the Client	SAGT.
Project Feature	Non-destructive testing, visual inspections, Preparation of BOQ, Remedial Measures for repairs.
Position Held	NDT In Charge.
Activities Performed	Non-destructive testing, visual inspections, preparation of audit report, remedial measures for repair and BOQ with supporting calculations

Name of the Project	NDT & Condition Assessment of Heavily Loaded Pipe Rack's Column, Beams & Sleepers at Finolex Industries, Ratnagiri.
Year	2023
Location	Ranpar, Ratnagiri.
Name of the Client	Finolex Industries Ltd..
Project Feature	Non-destructive testing, visual inspections, Preparation of BOQ, Remedial Measures for repairs.
Position Held	Project Manager.
Activities Performed	Non-destructive testing, visual inspections, preparation of audit report, remedial measures for repair and BOQ with supporting calculations

Name of the Project	Condition assessment & Structural Stability of Pre-Heater Building.
Year	2024
Location	Gondal, Gujarat.
Name of the Client	Unity Cement Pvt Ltd.
Project Feature	Non-destructive testing, visual inspections, Preparation of BOQ, Remedial Measures for repairs.
Position Held	Project Manager.
Activities Performed	Non-destructive testing, visual inspections, preparation of audit report, remedial measures for repair and BOQ with supporting calculations

• **RESPONSIBILITIES:**

- ✓ Preparation of proposals.
- ✓ Preparation of estimation.
- ✓ Meeting with clients.
- ✓ Site visits.
- ✓ On site execution.

- ✓ Structural Assessment.
- ✓ Supervision for NDT.
- ✓ Preparation of NDT reports.
- ✓ Preparation of Structural Assessment reports.
- ✓ Preparation of tentative estimations for repair.
- ✓ Preparation of rehabilitation measures.
- ✓ Resolve Customer Issues.
- ✓ Expand Customer Base.

#### KEY SKILLS

- ❖ Open Challenges & Opportunities.
- ❖ Easy adaptability to new situations.
- ❖ Good Communication Skills.
- ❖ Quick Decision Making.
- ❖ Excellent in Team Co-Ordination.

#### HOBBIES

- Listening Music.
- Reading Books.

#### DECLARATION

I hereby declare that all the information furnished above is true to the best of my knowledge and brief.

Date : \_\_\_\_\_

Place : \_\_\_\_\_